

2.3.3 Torsional (Shear) Wave Propagation in Thin Rods.....	19
2.3.4 Flexural Wave Propagation in Thin Rods.....	20
2.4 Dispersion.....	23
2.5 The Discrete and Fast Fourier Transforms.....	23
2.5.1 The Fourier Phase Method.....	27
2.6 The Short Kernel Method.....	27
3. The Bending Wave Testing Procedure.....	30
3.1 Overview.....	30
3.1.1 The Bending Wave Testing Procedure.....	31
3.1.2 Energy Source (Impact Device).....	31
3.1.3 Sensors.....	33
3.1.4 Signal Acquisition.....	34
3.1.5 Signal Processing Tools.....	35
3.2 Stress Wave Parameters Used for Condition Assessment.....	36
3.2.1 Wave Speed and Phase Velocity.....	36
3.2.2 Attenuation Ratio.....	36
3.2.3 Dominant Frequency and Centroid Frequency.....	38
3.3 Determining the Wave Speed.....	38
4. Development of a Standard Impact Device.....	44
4.1 Importance of Impact Device Selection.....	44
4.2 Creating an Effective Impact.....	45
4.3 Evaluation of Various Impact Devices.....	45
4.3.1 Experimental Setup.....	46
4.3.2 Comparison of Wave Propagation Properties.....	47
4.3.2.1 Impact-to-Impact Variations.....	49